

Oil Field Environmental Incident Summary

Incident: 20151026101627

Date/Time of Notice: 10/26/2015 10:16

Responsible Party: Unknown

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: SYVERSON 1-1H

Field Name: EAST FORK

Well File #: 21775

Date Incident: 10/25/2015

Time Incident: 10:45

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 100

Sec: 1

Qtr:

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Shane Knuchel

Unknown

Unknown, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine					22	barrels
Other	300	Barrels	280	Barrels	258	barrels

Description of Other Released Contaminant:

Type of fluid spilled is unknown at this time. CLR is investigating

Inspected:

Written Report Received: 11/27/2015

Clean Up Concluded: 11/13/2015

Risk Evaluation:

None

Areal Extent:

All fluid contained on constructed well pad.

Potential Environmental Impacts:

Well site soil.

Action Taken or Planned:

Standing fluid was sucked up using a vac truck. Soil samples will be taken to determine further cleanup action.

Wastes Disposal Location: TBD

Agencies Involved: Notified Mark Bins NDIC by phone on 10/26/2015 at 10:14 AM

Updates

Date: 10/27/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on well pad, but due to large quantity and unknown fluid, more followup is required.

Date: 12/1/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site 11:47 a.m. The weather was sunny, 18°F, with wind from the west 0-5 mph. There appear to be a couple of scraped areas on the pad area. I did not see any staining from the oil. Could not see anything from the spill released off the pad. There is some erosion to the pad in the southwest corner and into the field. NDIC Oil & Gas retains oversight. 48.37246,-103.48360